From:

Steve Demczak

To:

Dennis Ware; Suzanne Steab

Date: Subject: 5/11/2010 6:45 AM April Inspections

**Attachments:** 20100511070122.pdf; 20100511070145.pdf; 20100511065536.pdf



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE Lieutenant Governor

Representatives Present During the Inspection:							
Company	Dennis Ware Controller	•					
Company	Steve Demczak Environmental Scientist III	-					

# **Inspection Report**

Permit Number:	C0070006
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, April 27, 2010
Start Date/Time:	4/27/2010 2:00:00 PM
End Date/Time:	4/27/2010 4:00:00 PM
Last Inspection:	Tuesday, March 23, 2010

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 50's, Windy InspectionID Report Number: 2343

**Types of Operations** 

Accepted by: jhelfric

5/6/2010

Permitee: PLATEAU MINING CORP Operator: PLATEAU MINING CORP

Site: STAR POINT MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

**Current Acreages** 

<b>Total Permitted</b>	
<b>Total Disturbed</b>	113.34
Phase I	113.34
Phase II	95.30
Phase III	5.64

Mineral Ownership

**✓** Federal ✓ Underground ☐ Surface ✓ State ☐ Loadout County Fee Processing ☐ Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Monday, May 03, 2010

Date

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 27, 2010

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	$\checkmark$		$\checkmark$	
2.	Signs and Markers	~		V	
3.	Topsoil	<b>Y</b>		<b>V</b>	
4.a	Hydrologic Balance: Diversions	<b>✓</b>		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	✓		✓	
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	V		<b>V</b>	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				П

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 27, 2010

Page 3 of 3

## 1. Permits, Change, Transfer, Renewal, Sale

The permittee has submitted a Phase III bond release for a section of land for gas drilling by Conoco Philips.

## 2. Signs and Markers

The identification signs is next to the road to the site.

#### 3. Topsoil

All topsoil was used for reclamation.

## 4.a Hydrologic Balance: Diversions

Diversions were inspected and were functioning as designed.

#### 8. Noncoal Waste

The reclaim site is clear of non-coal waste material.

#### 12. Backfilling And Grading

No slides were noticed during the inspection.

## 18. Support Facilities, Utility Installations

There are no facilities.